

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection

Re-inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Visit

Verification of Closure

Status Change

Name of School: APEX MIDDLE SCHOOL

Location Address: 400 E MOORE ST

Mailing Addr: 400 E MOORE ST

City: APEX

State: NC

Zip: 27502-1927

City: APEX

State: NC

Zip: 27502-1927

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	10
TOTAL	1000	100

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)

Comment Addendum to Inspection Report

Establishment Name: APEX MIDDLE SCHOOL

Establishment ID: 4092440048

Date: 05/20/2025 **Time In:** 10:00 AM **Time Out:** 1:00 PM

Observations and Corrective Actions

3	Repair out of order drinking fountain in the hallway besides boys bathroom #1702. The spray nozzle on this fountain has poor water flow for drinking. Repair major plumbing leak beneath drinking fountain on the top floor hallway of building (B) near room #2206. Reattach loose side cover panel on drinking fountain in the gym lobby.
4	Repair one nonfunctional toilet and one nonfunctional urinal in the gym boys locker room bathroom. Repair the end toilet in boys bathroom #1702. This toilet has no water flow for flushing. Repair one toilet that is clogged and nonfunctional in girls bathroom #1406. Repair the end toilet in boys bathroom #2226 in building (B). This toilet is nonfunctional.
5	Repair two sinks that have clogged drain pipes in tech. education classrooms #0213 and #0213A
6	Repair roof and ceiling leaks in the following school building locations: in the cafeteria dining room, over the cafeteria food service line, in the cafeteria kitchen around the vent hood, in classroom #2110, in office #1206B, in the top floor hall of building (B) near room #2216, in the top floor hall of building (B) around the skylight window, and in the top floor hallway of building (B) above the student lockers near room #2218. Replace water damaged and water stained ceiling panels in the listed ceiling leak locations after the sources of the ceiling leaks have been fixed. Repair and repaint water damaged lower wall surface caused by the roof leak around the skylight window on the top floor hallway of building (B). Repair clogged floor drain for washing machine in the cafeteria kitchen laundry room. Standing water is covering the floor in this laundry room. Priority repairs for safety are needed due to the wet laundry room floor being a slip and fall hazard and the power cord for the washing machine being in standing water which creates possible electrical hazards. Repair clogged floor drain in the coaches office/first aid room #1413 in the gym. This floor drain periodically backs up and overflows. There is a sewer gas odor coming from the shower and bathroom floor drains in the gym girls locker room bathroom. These three floor drains should be flushed out weekly with water by custodial staff. These floor drain pipes should also be cleared of any blockages and buildup by building maintenance. Remove and replace three broken glass mirror panels from the wall of the fitness classroom #1701 A. Priority repairs for safety are needed.
8	Repair poorly functioning air conditioning systems throughout all of the hallways, classrooms, offices, and bathrooms of building (H). The ceiling ventilation ductwork in the gym girls locker room and bathroom/shower room is covered with build up and residue stains from moisture condensation and humidity. The ceiling ventilation ductwork should be cleaned of these stains and should be repainted with a water proof and mold resistant paint after cleaning.
11	Cockroaches are present throughout buildings (A) and (H) and are being spotted frequently by staff. Pest control treatments are needed throughout both buildings to remove the presence of the roaches.

Additional Comments

GC: Repair nonfunctional elevator in building (B). Repair of the elevator is necessary to provide handicap accessibility for both students and staff and to allow custodial staff to perform building maintenance and cleaning efficiently.