

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?

Inspection

Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: APEX FRIENDSHIP MIDDLE SCHOOL

Location Address: 7701 HUMIE OLIVE RD

Mailing Addr: \_\_\_\_\_

City: APEX

State: NC

Zip: 27502

City: \_\_\_\_\_

State: \_\_\_\_\_

Zip: \_\_\_\_\_

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>70</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

J D - REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)

## Comment Addendum to Inspection Report

**Establishment Name:** APEX FRIENDSHIP MIDDLE SCHOOL

**Establishment ID:** 4092440473

**Date:** 03/26/2025 **Time In:** 12:30 PM **Time Out:** 3:30 PM

### Observations and Corrective Actions

4	Repair three out of order toilets in the following school bathrooms: in girls bathroom #3112, ( one toilet that has a clogged drain and is backing up in the second stall), in girls bathroom #2112, (one nonfunctional toilet in the end stall), and in boys bathroom #2110, (one nonfunctional toilet). In boys bathroom #2209 the exposed metal support frame for the removed wall mirror has become bent and damaged. This exposed and damaged metal frame has sharp edges that could be an injury hazard. The metal frame should be removed from the boys bathroom wall as a safety precaution.
6	Reinstall and repair loose pane in window on the third floor hallway across from custodial closet #3004. There is a large crack around this loose window pane which could allow rainfall into the building and cause possible water damage. There is also a risk this loose window pane could break in strong winds. Priority repairs are needed to prevent greater damage. Repair the causes of roof and ceiling leaks in the following school building locations: over the stairs located in the front entry lobby, in the hallway by the entrance to classroom #1426, and in the front office conference room #1310. Water stained ceiling panels caused by these ceiling leaks should be replaced after the sources of the leaks have been repaired.
8	Repair broken, damaged, and loose baseboard heating system in the #1200 hallway student commons adjacent to the lockers and across the corridor from the entrance of stairway #S-4. This damaged baseboard heater is also adjacent to the glass exterior exit doors.

### Additional Comments

GC: School facility sanitation inspection completed.