

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection

Re-inspection

Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Visit

Verification of Closure

Status Change

Name of School: FELTON GROVE HIGH SCHOOL

Location Address: 5100 THRIFTWOOD DRIVE

Mailing Addr: 111 CORNING ROAD, SUITE 190

City: APEX State: NC Zip: 27539

City: CARY State: NC Zip: 27518

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>75</b>

Additional Comment Sheet Attached

Yes  No

Inspection by: J. D. REAS

EHS 1746 - Dunn, Jason

## Comment Addendum to Inspection Report

**Establishment Name:** FELTON GROVE HIGH SCHOOL

**Establishment ID:** 4092440585

**Date:** 08/13/2025 **Time In:** 10:00 AM **Time Out:** 2:00 PM

### Observations and Corrective Actions

3	Repair drinking fountains that are nonfunctional in the following locations: at the entry of the gym #1501, in the level #1 Area (A) commons, and beside the entrances of boys and girls bathrooms #00225 and #00227. A total of six fountains require repair.
4	Repair toilets and urinals that are nonfunctional due to a clogged and backed up sewage drain line in the boys and girls bathrooms #1105 and #1107. A total of 12 urinals and toilets in these restrooms are currently out of order. Priority plumbing repairs are required. Repair one urinal that is nonfunctional in the stadium home side men's restroom #1101. This out of order urinal is second in the row.
6	Repair and stop the sources of the roof leaks present throughout the main gym. Replace broken window pane by the exterior exit door in art classroom #0617
8	Repair and stop the sources of the air conditioning system condensation leaks that are present above the drop ceilings in classroom #1603, in lab classroom #2221, in lab classroom #2223, in lab classroom #1223, and in the lab class stock room #1221A. Replace water stained ceiling panels caused by these leaks. Repair the nonfunctional air conditioning system in the art class #0617 kiln room.

### Additional Comments

GC: Sanitation inspection report for a new school facility.