

Demerit Score: 24

Date of Insp/Chg: 04/14/2025
Status Code: A

Health Department 92
Current Facility ID 4092500555
Old Facility ID _____

Inspection of Swimming Pool

Water Supply: Municipal/Community On-Site Supply
Wastewater: Municipal/Community On-Site System

Water sample taken today?
 Yes No

Inspection Name Change
 Re-inspection Verification of Closure
 Visit Status Change

Name of Establishment: SCOTTS MILL POOL
201 SCOTTS RIDGE TRAIL, 5300 ATLANTIC AVENUE
Location Address: SUITE 101

Pool Operator: Braxton Wilson
(F, L)

Mailing Addr. 160 NE MAYNARD ROAD, STE. 210

City: APEX **State:** NC **Zip:** 27502

City: CARY **State:** NC **Zip:** 27513

* Indicates critical item (6-point demerit)

WATER QUALITY: (.2535)

- *1. Water clear enough to clearly see bottom of pool and pool drain 6
- *2. Disinfectant residual provided by:
 - free chlorine = 8.0 (at least 1.0 ppm or 2.0 ppm where required);
 - bromine = (at least 2.0 ppm); or
 - biguanide = (30 to 50 ppm)..... 6
- *3. Pool water pH = 7.2 (7.2 to 7.8)..... 6
- *4. Water temperature of heated pool °F; does not exceed 90°F
(swimming pool) or 104°F (spa) 6
- 5. Daily written records of water quality and test kit kept on site 4

Comments:

**** SEE COMMENT SHEET ATTACHED ****

POOL MAINTENANCE:

- *6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=480 Field verification complete=Yes 6
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)... 4
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) 4
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537)..... 4
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523)..... 2
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521)..... 2
- 12. Inlets and other fittings in place and in good repair (.2537)..... 4
- 13. Contrasting band on steps and benches (.2521, .2516, .2532)..... 4
- 14. Spa timer working properly (.2537)..... 4

PREMISES:

- *15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) 6
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) 4
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537)..... 4
- 18. Lifeguards present or warning signs posted (.2530) 4
- 19. Signs prohibit glass containers or pets in pool area(.2530) 4
- 20. Caution signs posted at hot water spas (.2532) 4
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ... 4
- *22. Emergency telephone provided (.2530) 6

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) 4
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) 4
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) 2
- 26. Valves and pipes identified by color codes or labels (.2518) 2
- 27. Filter backwash discharged through an air gap (.2513) 2

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) 2
- 29. Required fixtures provided, clean, and in good repair (.2526) 2
- 30. Approved water source, no cross connections (.2512) 2
- 31. Sewage disposed of in a properly operating sewage system (.2513) 2
- 32. Floors smooth, slip-resistant, kept clean(.2526) 2
- 33. Hose bibbs and floor drains provided (.2526) 2

Comment Sheet Attached

Yes No

Report Received by:



Inspection Conducted by: Maria Powell

EHS I.D. # 2587 - Powell, Maria

Comment Addendum to Inspection Report

Establishment Name: SCOTTS MILL POOL

Establishment ID: 4092500555

Date: 04/14/2025 **Time In:** 2:15 PM **Time Out:** 3:45 PM

Observations and Corrective Actions

- 5 2535. Pool chemistry records have not been recorded at this time. Records shall be taken 2 times daily.
- 7 2537. Observed soil debris inside pool. Pool walls and floors shall be kept clean.
- 8 2537. Observed debris in skimmer baskets. Surface skimmers shall be provided with weirs and maintained clean.
- 11 .2537 Observed sharp metal plates placed on top of handrail. Plates moved to avoid safety hazard. Handrails shall be good repair.
- 17 .2537.Observed chair within 3 feet of deck ledge. A minimum of 6 feet of deck clearance is required.
- 24 .2518.Two lights burned out inside pump room. Repair lighting.Observed damaged walls and floors inside pump room. Equipment shall be in good repair.
- 29 Observed hot water 116F inside restrooms How water shall be a maximum of 110F. Adjust hot water temperatures.

Additional Comments

Observed additional pump in pump room that is not in use. Observed the breaker to this pump turned off during the inspection. More details available on VGB letter.

In regards to the bonding wire, No imminent hazard found in pump room at time of inspection. Visible bonding wire attached and intact to pump. Have an electrician evaluate all the components to determine function, if not done so prior to permitting inspection. If an electrician finds a repair is needed, obtain an electrical permit from the appropriate municipality, and have the corrections inspected. Flow rate of pump = 480gpm