

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today?

Inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: APEX ELEMENTARY SCHOOL

Location Address: 700 TINGEN RD

Mailing Addr: 700 TINGEN RD

City: APEX State: NC Zip: 27502-2053

City: APEX State: NC Zip: 27502-2053

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	30
TOTAL	1000	80

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



Comment Addendum to Inspection Report

Establishment Name: APEX ELEMENTARY SCHOOL

Establishment ID: 4092440047

Date: 05/16/2025 **Time In:** 10:00 AM **Time Out:** 1:00 PM

Observations and Corrective Actions

4	Repair toilet in the bathroom in classroom #208. This toilet has poor water flow for flushing. Repair nonfunctional toilet in the bathroom in classroom #308. Priority repairs are needed to bring this toilet back online. Replace broken wall base tiles adjacent to the urinals in boys bathroom #409A.
6	Repair the causes of the roof and ceiling leaks present in the following school locations : in the gym, in the media center, in classroom #402, in the hallway at the entrance into the 400 hall and by the entrance of stairway #400B, and in class trailer #4. The ceiling leaks in classroom #402 are major and require priority repair. Water stained, water damaged, and missing ceiling panels caused by these roof leaks should be replaced after the roof leaks have been fixed and stopped. Replace deteriorated and rotted floor boards on the entry ramp of class trailer #4. Replace broken hand railing on the entry ramp of class trailer #4. Priority repairs for safety are needed on both the deteriorated floorboards and broken handrailing of the trailer #4 ramp to prevent possible trip and fall injury hazards. Replace broken latch on the hall door for classroom #308. This door currently cannot be closed or locked in the event of emergency.
11	Repair and reattach loose barrier panel on the elevated platform of the play structure on the 3-5 playground behind the gym. This loose panel is missing fastener bolts to hold it securely in place. Repair areas of torn ground cover padding around the play structures on the 1st through 2nd grades playground beside the baseball field. Repairs for safety are necessary to prevent trip and fall injuries. Weeds, shrubs, and undergrowth were growing all along the main building foundations including behind the gym, along the 500 hallway, by the 300 hall exit, and at the 3-5 hall exit. Grass was very high at 10 inches or greater in height in many areas across campus including between and around the class trailers, along the bus loop, at the exit of the 300 hall, adjacent to the school building and on top of the retaining wall at the 3-5 exit, and adjacent to the main driveway entrance and sidewalk. Vines are covering the retention wall adjacent to the sidewalk and exit of the 3-5 hallway. Proper mowing and trim work is necessary to clean up the school premises. This mowing and trimming is also needed to prevent pest harborage areas on the school campus.

Additional Comments

GC: School facility sanitation inspection completed.