

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today?

Inspection

Name Change

Yes No

Re-inspection

Verification of Closure

Wastewater: Municipal/Community On-Site System

Visit

Status Change

Name of School: WEST LAKE MIDDLE SCHOOL

Location Address: 4600 WEST LAKE RD

Mailing Addr: 4600 W LAKE RD

City: APEX

State: NC

Zip: 27539-7657

City: APEX

State: NC

Zip: 27539-7657

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	
TOTAL	1000	90

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)

Comment Addendum to Inspection Report

Establishment Name: WEST LAKE MIDDLE SCHOOL

Establishment ID: 4092440091

Date: 03/31/2025 **Time In:** 1:00 PM **Time Out:** 4:00 PM

Observations and Corrective Actions

3	Repair out of order drinking fountain on the 500 hallway across from girls bathroom #501. This out of order fountain has a clogged drain pipe and is backing up. Priority plumbing repairs are required.
4	Repair out of order toilets and urinals in the following school bathrooms: in girls bathroom #501, (one nonfunctional toilet in the third stall that has poor water flow for flushing), in boys bathroom #512, (one nonfunctional urinal at the end of row that has poor water flow for flushing), in boys bathroom #305, (one nonfunctional urinal and one nonfunctional toilet), in boys bathroom #709, (two nonfunctional urinals), and in boys bathroom #610, (one nonfunctional urinal). Priority plumbing repairs are needed to bring these out of order bathroom fixtures back online.
5	Repair nonfunctional hand wash sink in the staff bathroom adjacent to the sixth grade assistant principal's office #311. This nonfunctional hand wash sink has a clogged drain pipe and is backing up. Priority plumbing repairs are needed to fix this hand sink.
6	Replace torn stair step tread covering on the edge of the steps in stairway #215. Priority repairs for safety are required to prevent possible trip and fall injuries. Reattach loose stair step tread plate on the edge of the steps of the exterior stairway that connects the bus loop to the front entrance of the school building. Priority repairs for safety are required due to the potential of trip and fall injuries.
8	Repair nonfunctional air conditioning systems in the following school building classrooms: in classroom #712, in classroom #714, in classroom #720 and in classroom #721.

Additional Comments

GC: The electrical wall outlet in classroom #714 is sparking whenever it is plugged in . Priority electrical repairs for safety are required on this wall outlet.