

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection  Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: SALEM ELEMENTARY SCHOOL

Location Address: 6116 OLD JENKS RD

Mailing Addr: 6116 OLD JENKS RD

City: APEX

State: NC

Zip: 27523-8242

City: APEX

State: NC

Zip: 27523-8242

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	30
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	15
<b>TOTAL</b>	<b>1000</b>	<b>100</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

*J. D. REHS*

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



## Comment Addendum to Inspection Report

Establishment Name: SALEM ELEMENTARY SCHOOL

Establishment ID: 4092440199

Date: 05/28/2025 Time In: 10:00 AM Time Out: 12:30 PM

### Observations and Corrective Actions

4	Repair urinal that has a clogged drain in the 800 modular boys bathroom. Repair torn carpet at the entrance into modular 800 boys bathroom. Priority repairs for safety on the torn carpet are necessary due to it being a possible trip and fall hazard. Repair the first toilet in row in the modular 800 girls bathroom. This toilet has poor water flow for flushing. Repair the toilets in classroom bathrooms #203A and #211A. These two toilets have very poor water flow for flushing. Repair and reattach loose wall base tile strips in class bathrooms #208A, #212A, and in #216A. Repair or replace torn wall paper covering in class bathroom #208A. Replace broken ceiling panel in the special needs class kitchen bathroom #404A.
6	Repair the sources of roof and ceiling leaks in following school locations: in the media center on the lower ceiling by the wall book cases, in the rear exit lobby at the end of the 300 hall, in the 300 hallway near the front office, in the special needs class kitchen #404, and in class trailer # 603. The sources of these roof and ceiling leaks should be identified, repaired and stopped. The water stained and water damaged ceiling panels in these leak locations should be replaced after the leaks have been fixed. Repair and stop the leaks present around the window frame and window sill in classroom trailer #603. The water damaged and water stained interior wall panels beneath this leaking window should be removed and replaced after the leaks have been fixed. Water soaked and stained interior wall insulation beneath the window leaks should also be removed and replaced after leak repairs have been completed. Replace broken and missing floor tiles also in class trailer #603. Replace broken floor plank on the top step of the exterior front ramp deck entry stairs of class trailer #602. Priority safety repairs are required on this broken stair step due to the potential of trip and fall injuries. Replace rotted floor plank on the front entry ramp deck of trailer #604. Priority repairs for safety are required due to the potential of this deteriorated deck floor board collapsing under foot. Replace loose, warped, and deteriorated floorboards on the front entry ramps of class trailers #604, #601, and modular #800. Repairs for safety are necessary to prevent trip and fall injuries. Repair loose railing beams on class trailers #604 and #601. Repairs for safety are required to prevent fall hazards and due to possible injuries from exposed nails on the loose railings.
8	Repair nonfunctional air conditioning system in class trailer #602. Priority repairs are needed to bring the air conditioning system in this class trailer back online for the hot weather season .
11	Remove or replace broken tube climbing cable ladder and climbing cable mesh on the playground structure adjacent to the 800 modular building. Priority repairs for safety are required due to the potential of injuries from falls on this broken playground equipment.

### Additional Comments

GC: School facility sanitation inspection completed.