

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection  Name Change

Yes  No

Re-inspection

Verification of Closure

Wastewater:  Municipal/Community  On-Site System

Visit

Status Change

Name of School: MIDDLE CREEK ELEM. SCHOOL

Location Address: 110 MIDDLE CREEK PARK AVE

Mailing Addr: 110 MIDDLE CREEK PARK AVE

City: APEX State: NC Zip: 27539

City: CARY State: NC Zip: 27560

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>105</b>

Additional Comment Sheet Attached

Yes  No

Inspection by: JTD - REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)

## Comment Addendum to Inspection Report

**Establishment Name:** MIDDLE CREEK ELEM. SCHOOL

**Establishment ID:** 4092440200

**Date:** 03/31/2025 **Time In:** 9:45 AM **Time Out:** 12:45 PM

### Observations and Corrective Actions

3	Repair nonfunctional drinking fountain in hallway besides entrance of girls bathroom #153.
4	Repair out of order toilets and urinals in the following student bathrooms: in girls bathroom #153, (one toilet that is in the second to last stall that has poor water flow for flushing), in boys bathroom #226, (one urinal that is at the end of row and has no water flow for flushing), and in classroom bathroom #318A, (one toilet that has poor water flow for flushing and that is leaking on the flush valve). Repair and repaint damaged wall surfaces behind and beside of toilets in the following class and staff bathrooms: in class bathroom #306A, in class bathroom #316A, in class bathroom #320A, in class bathroom #322A, in class bathroom #324A, and in staff bathroom #124. Repair water damaged base of wall and replace loose base tile beneath urinals in the modular building #M824-02 boys bathroom. Repair and seal over halls in the lower stall walls in the modular building girls bathroom #R808-03A.
5	Repair and reattach one faucet that is out of order and loose on the hand wash sink basin at the entrance of boys bathroom #155.
6	Repair the sources of ceiling leaks present in the following school locations: in the gym/multi-purpose room #206 beside the ceiling air conditioning vents, in the ramp corridor room #202A that leads from the gym floor to the stage, and in the hallway adjacent to mechanical room #158. Replace water stained ceiling panels in these leak locations after the sources of the ceiling leaks have been fixed. Reattach loose lower railing to the support post on the front entrance ramp of the modular class building #R808. Priority repairs for safety are needed to prevent possible trip and fall injuries.
8	Repair nonfunctional air conditioning systems in all of the media center #144 rooms and offices. Dust build up and residue is covering the ceiling vents in the gym/multipurpose room #206. A lift is needed to clean these ceiling vents due to the height of the gym ceiling.

### Additional Comments

GC: Build up and residue is covering the pre-k playground equipment and sunscreen awning. Pressure wash cleaning of this playground equipment and awning is needed.