

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection

Re-inspection

Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Visit

Verification of Closure

Status Change

Name of School: MIDDLE CREEK HIGH SCHOOL BLG

Location Address: 123 MIDDLE CREEK PARK AVE

Mailing Addr: 123 MIDDLE CREEK PARK AVE

City: APEX

State: NC

Zip: 27502

City: APEX

State: NC

Zip: 27502

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	30
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>85</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

J D REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



## Comment Addendum to Inspection Report

**Establishment Name:** MIDDLE CREEK HIGH SCHOOL BLG

**Establishment ID:** 4092440226

**Date:** 05/21/2025 **Time In:** 10:00 AM **Time Out:** 1:00 PM

### Observations and Corrective Actions

4	Repair out of order toilets and urinals in the following student restrooms: in boys bathroom #3207, (two toilets that are out of order due to major drainpipe clogs), in boys bathroom #3307, (one toilet that is out of order due to a clogged drainpipe), in the girls bathroom #2208, (one toilet that is out of order due to a clogged drainpipe and two toilets that are loose at the base of the fixtures on the floor), in the boys bathroom on the 500 hall by the lunchroom, (one nonfunctional urinal), and in boys bathroom #308, (one nonfunctional urinal). A total of eight toilets and urinals require repairs in the student bathrooms. Replace three broken off toilet stall doors in the following boys bathrooms: in boys bathroom #308, in boys bathroom #2208, and in boys bathroom #2308. One broken off toilet stall door in each of the listed bathrooms.
6	Repair major roof leaks in the auditorium. These roof leaks have damaged the overhead ceiling acoustical panels. These panels are deteriorated and stained from the water damage. There is also water stained ceiling panels in the auditorium as a result of these roof leaks. The sources of all the roof leaks in the auditorium should be identified, repaired, and stopped. The water damaged ceiling panels and ceiling acoustic panels in the auditorium should be replaced. Roof and ceiling leaks are also present in the cafeteria dining room near the upper wall skylight window that is adjacent to the food service line. The wall beneath this skylight has water damage and water stains. The sources of the roof leaks around the skylight windows in the cafeteria should be located, fixed, and stopped. The water damaged wall surface beneath the skylight should be repaired and repainted after the leaks are fixed. Replace water stained ceiling panels that were caused by a prior leak, in the 400 hallway, along the wall adjacent to classroom #430.
8	Repair completely nonfunctional air conditioning systems present in both classroom trailer #5 and classroom trailer #6.

### Additional Comments

GC: School facility sanitation inspection completed.