

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection  Name Change

Yes  No

Re-inspection

Verification of Closure

Wastewater:  Municipal/Community  On-Site System

Visit

Status Change

Name of School: ST MARY MAGDALENE SCHOOL

Location Address: 625 MAGDALA PL

Mailing Addr: 625 MAGDALA PL

City: APEX State: NC Zip: 27502

City: APEX State: NC Zip: 27502

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>65</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

*J D - REHS*

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



## Comment Addendum to Inspection Report

**Establishment Name:** ST MARY MAGDALENE SCHOOL

**Establishment ID:** 4092440242

**Date:** 12/09/2024 **Time In:** 10:30 AM **Time Out:** 1:00 PM

### Observations and Corrective Actions

- 4 Repair urinal that is nonfunctional due to major plumbing leaks in the boy's locker room bathroom in the gym. Repair toilet that has poor water flow for flushing in the 2nd stall in the girls hall bathroom on the top floor of the activity building. Repair ceiling leaks in the girls hall bathroom on the first floor of the main school building by the lobby and in the girls hall bathroom on the lower level floor of the activity building. Replace water stained ceiling tiles in these girls bathrooms after the causes of the ceiling leaks have been fixed.
- 5 Repair nonfunctional hand wash sink in the work room adjacent to the student bathroom for the Pre-K #3 classroom.
- 6 Repair ceiling leaks in the following school locations: in the art class kiln room, and in the hallway entrance for the boys bathroom on the lower floor level of the activity building. Replace water stained and missing ceiling tiles in these locations after the causes of the ceiling leaks have been fixed.

### Additional Comments

The exhaust pipe on the back of the Kiln for the art classroom vents heat, gases, and dust from the exhaust pipe directly into the kiln room. School administration may want to check with the local municipal fire marshal to see if building codes require the kiln exhaust pipe to have a hose pipe attachment that vents the heat, dust, and gases from the kiln when in use to the outside of the building to prevent possible issues with interior air quality.

School facility sanitation inspection completed.