

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection  Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: LAUREL PARK ELEMENTARY SCHOOL

Location Address: 2450 LAURA DUNCAN RD

Mailing Addr: 2450 LAURA DUNCAN RD

City: APEX

State: NC

Zip: 27523

City: APEX

State: NC

Zip: 27610

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>90</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



## Comment Addendum to Inspection Report

**Establishment Name:** LAUREL PARK ELEMENTARY SCHOOL

**Establishment ID:** 4092440303

**Date:** 02/17/2025 **Time In:** 1:30 PM **Time Out:** 4:00 PM

### Observations and Corrective Actions

- 3 Repair nonfunctional drinking fountain on the top floor hallway across from classroom #2303.
- 4 Repair toilet in the end stall of the top floor boys bathroom #2210. This toilet has a clogged sewer drain line that is causing the toilet to back up and flood the bathroom floor. Priority repairs are needed. The flooding caused by this backed up toilet is causing water damage to the ceiling in the ground floor boys bathroom #1212 beneath. The water stained and water damaged ceiling surface in boys bathroom #1212 should be repaired and repainted after the clogged and backing up toilet in boys bathroom #2210 above it has been fixed. Repair the toilet in the 2nd stall of boys bathroom #1212. This toilet also has a clogged sewage drain pipe and is backing up. Repair the toilet in the first stall of girls bathroom #1210. This toilet leaks on the plumbing pipework when flushed. Repair two toilets that are out of order in girls bathroom #2208 due to leaks on the plumbing pipework on both toilets. Repair urinal that is out of order in boys bathroom #2508 due to a clogged sewage drain line causing the urinal to back up. Repair deteriorated and damaged base of wall behind toilet in classroom bathroom #1407A. The floors in all student bathrooms have a buildup or residue and require regular daily cleaning by the assigned cleaning crew. The floor in bathroom #1212 also had an odor and is need of regular cleaning by the assigned cleaning staff.
- 6 Replace two large missing ceiling panels in the cafeteria dining room. Replace nine large missing ceiling panels in the gym. Priority replacement of these missing ceiling panels is needed to due the large areas of uncovered ceiling space in both the cafeteria and gym. Repair and repaint water stained wall surface next to countertop hand wash sink in classroom #1401.
- 8 Repair nonfunctional heating system in classroom trailer #2. The upper wall emergency light fixture in the cafeteria dining room has become detached from the wall and is hanging loosely by wiring. Repair and reattach this emergency light fixture to the wall. Dead bugs are present in the ceiling light fixture in classroom bathroom #1405A. The interior of this light fixture should be cleaned to remove the dead bugs.

### Additional Comments

Replace broken plastic ground border frame around the perimeter of the K-2 playground structure.