

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection

Re-inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Visit

Verification of Closure

Status Change

Name of School: LAUREL PARK ELEMENTARY SCHOOL

Location Address: 2450 LAURA DUNCAN RD

Mailing Addr: 2450 LAURA DUNCAN RD

City: APEX State: NC Zip: 27523

City: APEX State: NC Zip: 27610

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	30
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	30
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	15
TOTAL	1000	95

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)

Comment Addendum to Inspection Report

Establishment Name: LAUREL PARK ELEMENTARY SCHOOL

Establishment ID: 4092440303

Date: 03/18/2026 **Time In:** 10:00 AM **Time Out:** 12:20 PM

Observations and Corrective Actions

4	Repair two nonfunctional urinals in boys bathroom #2508 and one nonfunctional urinal in boys bathroom #2210. All of the three listed nonfunctional urinals have clogged and blocked drain pipes and are backing up. Priority repairs are needed.
5	Repair two out of order handwash sinks in boys bathroom #1212. Both of these handwash sinks have broken hot water flow control valves beneath the sinks. Both of these sinks have extremely hot water flow that can not be adjusted due to the broken flow control valves. Priority repairs for safety are required due to the extreme hot water temps in these sinks being a potential scalding hazard. Repair one nonfunctional handwash sink due to a broken and loose faucet and a clogged drain in boys bathroom #2508. Repair one nonfunctional handwash sink due to a broken off water flow valve on the faucet in boys bathroom #2210. A total of four handwash sinks were out of order in student bathrooms at the time of inspection and in need of plumbing repairs.
6	Repair and stop the source of major ceiling leaks present in the shipping and receiving office #1308A and in the adjacent staff bathroom #1308B. These ceiling leaks appear to be adjacent to a ceiling sprinkler water supply pipe. Priority repairs are required due to large black stains being present on the drop ceiling panels in the leak locations. These stained ceiling panels should be removed and replaced after the sources of the leaks have been fixed. Replace missing ceiling panels in the gym and in the hallway at room #2305. Replace strips of lower wall base tile that have become loose and have missing sections on the school walls in the following locations: in the 5th grade hallway at the student bathrooms and drinking fountains, and on the second grade hallway on the half wall across from room #2105.
11	Remove the large stack of wooden pallets on the loading dock at the dumpsters. These wooden pallets should be removed from the school premises due to safety concerns that the stack of pallets could topple over and due to the potential for the stack of pallets to become a pest harborage area.

Additional Comments

GC: School facility sanitation inspection completed.