

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?

Inspection

Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: APEX HIGH SCHOOL

Location Address: 1501 LAURA DUNCAN RD

Mailing Addr: 1551 ROCK QUARRY RD

City: APEX

State: NC

Zip: 27502-1539

City: RALEIGH

State: NC

Zip: 27610-4145

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	20
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>105</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)

## Comment Addendum to Inspection Report

**Establishment Name:** APEX HIGH SCHOOL

**Establishment ID:** 4092440490

**Date:** 03/05/2025 **Time In:** 10:00 AM **Time Out:** 1:00 PM

### Observations and Corrective Actions

- 3 Repair a total of four fountains that are nonfunctional due to plumbing leaks in both the chorus classroom #1205 and in the adjacent orchestra classroom #1207. Each room has two fountains that are nonfunctional.
- 4 Repair and remove blockages from sewage lines that are causing frequent backups of waste water from the floor drains in both the boys hall bathroom #3116 and in the girls hall bathroom #3221. Repair one nonfunctional toilet due to leaks in class bathroom #1210C. Repair one nonfunctional urinal in the boys hall bathroom #1304. Repair one toilet at the end of the left row in girls hall bathroom #1302. This toilet leaks on the plumbing pipework when flushed. Repair one toilet in the special needs class kitchen bathroom #1403B. This toilet also leaks on the plumbing pipework when flushed. Repair two nonfunctional toilets each at the end of row in both the boys and girls bathrooms #3406 and #4406. One nonfunctional toilet in each bathroom. Repair the first toilet on the left side row at the hand wash sinks in the concession stand area women's bathroom #0327. The drain line for this toilet has a clog or blockage and the toilet backs up and overflows when flushed.
- 5 Reattach and secure loose hand wash sink fixture to the wall in boys hall bathroom #1219. Repair one sink that has a clogged drain line in classroom #1224. This sink is backing up when used due to this clogged drain.
- 6 Repair floor drain that is backing up frequently and overflows with waste water in the food service classroom utility space #1210D. There may be a blockage in the sewage line for this room that should be cleared out or if the food service classroom has a grease trap it may need to be cleaned out. Repair the cause of the ceiling leaks present in the food service classroom #1210. Repair the sources of ceiling leaks present in classroom #1402 and in the hallway by custodial closet #1321. Replace water stained ceiling panels caused by the ceiling leaks in these locations after the ceiling leaks have been fixed. There is hole in the wall behind the utility sink in classroom #1224. This hole had been cut into the wall to complete plumbing line repairs. A wall panel cover is needed to seal off the hole in this wall at the plumbing access point.
- 9 Repair shower head that has a constant and spilling leak in the girls teams locker room bathroom #1324.

### Additional Comments

Repair nonfunctional emergency shower and eyewash in the carpentry classroom #1232. Both fixtures have been shut off due to leaks. Priority repairs for safety are necessary to bring these emergency personal wash fixtures back on line.