

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection

Re-inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Visit

Verification of Closure

Status Change

Name of School: APEX FRIENDSHIP ELEMENTARY SCHOOL BUILDING

Location Address: 7901 HUMIE OLIVE RD

Mailing Addr: 5625 DILLARD DRIVE

City: APEX

State: NC

Zip: 27502

City: CARY

State: NC

Zip: 27518

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	10
TOTAL	1000	25

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

Comment Addendum to Inspection Report

Establishment Name: APEX FRIENDSHIP ELEMENTARY SCHOOL BUILDING

Establishment ID: 4092440538

Date: 04/01/2025 **Time In:** 9:30 AM **Time Out:** 12:00 PM

Observations and Corrective Actions

- | | |
|----|--|
| 6 | Repair the source of the ceiling leaks present in the hallway adjacent to the entrance of boys bathroom #1402. Replace water stained ceiling panels in this leak location after the ceiling leaks have been fixed. There are leaks present around the glass window framework in the breezeway adjacent to girls bathroom #1401. The floor at the base of these windows was wet from the prior nights rainfall. The framework around these windows should be sealed to prevent further leaks. Interior leaks from rainfall was also present in classroom #1204 by the exit door and adjacent windows and in the gym at the rear exterior exit doors. The window framework adjacent to the exit doorway in classroom #1204 should be sealed to prevent future leaks. The exit doors in the gym need rubber door sweeps installed at the base of both doors to keep rain water from flowing in beneath the doors. |
| 11 | Door sweeps are needed on the base of the glass exterior exit doors in the cafeteria dining room closest to the service line and on the base of the glass exterior entry/exit doors leading from the staff parking lot and into the hall by work room #1406. Visible cracks are present beneath these doors. The door sweeps should be installed to prevent areas where pests can enter the building. |

Additional Comments

GC: School facility sanitation inspection completed.