

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today?

Inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: THE MATH AND SCIENCE ACADEMY OF APEX

Location Address: 3501 DROPSEED DR

Mailing Addr: 104 TOWER VIEW COURT

City: APEX

State: NC

Zip: 27502

City: CARY

State: NC

Zip: 27513

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	35
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	
TOTAL	1000	90

Additional Comment Sheet Attached

Yes No

Inspection by:

J.D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



Comment Addendum to Inspection Report

Establishment Name: THE MATH AND SCIENCE ACADEMY OF APEX

Establishment ID: 4092440540

Date: 12/12/2025 **Time In:** 2:00 PM **Time Out:** 4:30 PM

Observations and Corrective Actions

3	Repair nonfunctional water dispenser on drinking fountain in the front lobby by the gym.
4	Repair nonfunctional toilet in the middle school girls bathroom #27. Repair one toilet that is leaking on the plumbing pipework at the rim of the fixture in girls hall bathroom #24.
5	Soap dispensers are missing at the hand wash sinks in the handicap toilet stalls in the middle school boys and girls bathrooms #27 and #29. Two soap dispensers should be installed. One at each hand wash sink in both of the handicap stalls. Reattach hand wash sink fixture that is loose and coming away from the wall in the bathroom in classroom #110.
6	Repair and stop the sources of the roof and ceiling leaks present in the media center and on the top floor back hallway adjacent to room #219. Replace the water stained ceiling panels caused by the ceiling leaks in these locations.

Additional Comments

GC: School facility sanitation inspection completed.