

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection

Re-inspection

Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Visit

Verification of Closure

Status Change

Name of School: TRIANGLE MATH AND SCIENCE ACADEMY HS CAMPUS APEX

Location Address: 3570 AMBERLIGHT ROAD

Mailing Addr: 3570 AMBERLIGHT ROAD

City: APEX

State: NC

Zip: 27502

City: APEX

State: NC

Zip: 27502

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	15
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	20
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>65</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

*J. D. REHS*

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



## Comment Addendum to Inspection Report

**Establishment Name:** TRIANGLE MATH AND SCIENCE ACADEMY HS CAMPUS APEX **Establishment ID:** 4092440571

**Date:** 11/04/2024 **Time In:** 10:00 AM **Time Out:** 1:00 PM

### Observations and Corrective Actions

- 4 Repair and seal hole in the wall by the hand wash sinks of the boys bathroom on the high school hallway. Repair the ceiling leak present in the gym stage dressing room bathroom. Replace the water stained ceiling panel in this bathroom after the cause of the leak has been fixed. Replace/install the missing door latch on the door of the second gym stage dressing room bathroom. Install the missing wall base tile that is absent in this same bathroom.
- 5 Repair and reattach five loose hand wash sink faucets in the following school bathrooms: four loose hand sink faucets in the boys high school hall bathroom and one loose hand sink faucet in the boys bathroom on the second floor hallway.
- 6 Repair roof and ceiling leaks in the following school locations: in the gym lobby at the front entrance doors, in the gym lobby hallway at the entrance to the girls bathroom, in the cafeteria dining room adjacent to custodial closet #134B, in the school library, in ramp corridor #6-122 that runs from gym floor to the stage, in the school principals office #200C, in the hallway at the entry to room #313I, on the second floor hallway by the sprinklers at the entrance to office #A-200, inside of classroom #208, and inside of classroom #302. Replace water stained and water damaged ceiling panels in these locations after the sources of these ceiling and roof leaks have been fixed.
- 9 Repair shower that has poor water flow for washing in the girls gym locker room.

### Additional Comments

The ice machine in the athletic program concession stand should be indirectly drained or air gapped above the floor sink drain to prevent the back flow of waste water from the floor sink drain into the ice machine bin.

Repair nonfunctional hot air blow dryer for hands in the cafeteria pantry staff bathroom.

Initial sanitation inspection of new school building completed.