

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection

Re-inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Visit

Verification of Closure

Status Change

Name of School: SALEM ELEMENTARY SCHOOL

Location Address: 6116 OLD JENKS RD

Mailing Addr: 6116 OLD JENKS RD

City: APEX

State: NC

Zip: 27523-8242

City: APEX

State: NC

Zip: 27523-8242

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	30
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	15
TOTAL	1000	115

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

Comment Addendum to Inspection Report

Establishment Name: SALEM ELEMENTARY SCHOOL

Establishment ID: 4092440199

Date: 05/26/2026 **Time In:** 11:15 AM **Time Out:** 2:15 PM

Observations and Corrective Actions

4	Sewage and wastewater is periodically backing up and out of the bathroom floor drains and onto the floors in the office health room bathroom #101A, in office staff bathroom #101H and in office staff bathroom #101J. This is per notice of school administration and custodial staff. The most recent sewage back up out of these bathroom floor drains was two weeks prior to the current school building sanitation inspection. The source of any blockages present in the floor drain pipework for these office restrooms should be removed to prevent future clogs, backups and wastewater overflows. Priority sanitation repairs are required. Repair one nonfunctional urinal in boys hall bathroom #202. Repair one toilet that has poor water flow flushing and is clogging frequently in class bathroom #215A. Repaint rusted and chipping wall columns and replace loose wall base tile behind the toilets in class bathrooms #205A, #207A, and #211A. Replace torn wall paper in class bathroom #214A.
5	Repair major leaks on the plumbing pipework beneath the countertop hand wash sink in classroom #506. Replace water damaged lower hand wash sink plumbing cabinet panels in classroom #506 after the leaks have been repaired.
6	Repair or replace loose, broken, rotted, deteriorated, and warped floor boards and handrails on the entry/exit ramps, decks, and steps of the following school trailers: class trailer #601, class trailer #602, class trailer #603, class trailer #702, class trailer #703, class trailer #M602 on the side ramp and back steps, and on the boys and girls bathroom trailer entrance ramps and deck. There is major damage to the entrance ramps and decks of the boys and girls bathroom trailer. Holes and broken floorboards are present on the ramps and deck of this student bathroom trailer. Priority repairs for safety are required on the bathroom trailer ramps and deck to prevent potential injury hazards. Replace broken and missing ceiling panels in the gym/multi-purpose room.
8	Repair nonfunctional air conditioning systems in the following school locations: in the main hallway of modular building #M602, in classroom #808 of modular building #M602, in classroom #504 in the main school building, and in the school media center/library.
11	Repair broken cables on the tube ladder and climbing net of the large play structure on the 3rd through 5th grade playground. Repairs for safety are required. The garden area adjacent to the pre-k playground is overgrown with high grass and weeds and requires mowing and trimming.

Additional Comments

GC: School facility sanitation inspection completed.