

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: SALEM MIDDLE SCHOOL

Location Address: 6150 OLD JENKS RD

Mailing Addr: _____

City: APEX

State: NC

Zip: 27523

City: _____

State: _____

Zip: _____

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	30
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	40
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	
TOTAL	1000	125

Additional Comment Sheet Attached

Yes No

Inspection by: J.D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



Comment Addendum to Inspection Report

Establishment Name: SALEM MIDDLE SCHOOL

Establishment ID: 4092440296

Date: 05/20/2026 **Time In:** 10:30 AM **Time Out:** 1:00 PM

Observations and Corrective Actions

3	Repair one nonfunctional drinking fountain on the ground floor #400 hallway adjacent to the media center and across from the entrance of stairway #2. Repair two nonfunctional drinking fountains on the second floor #2400 hallway across from the entrance of stairway #2. A total of three out of order drinking fountains were identified during inspection.
4	Replace missing seat on one toilet in the boys bathroom on the #200 hallway by the cafeteria dining room. Repair two toilets that are nonfunctional due to poor water flow for flushing. One nonfunctional toilet is in the left side end stall in the girls bathroom on the #500 hallway and the other one nonfunctional toilet is in the girls bathroom on the #400 hallway by the elevator. Repair one nonfunctional toilet in the boys bathroom on the #500 hallway by classroom #503. A total of four toilets were observed to be out of order and in need of repairs at the time of inspection.
5	Repair two hand wash sink drains that are clogged and backing in the girls bathroom on the #2500 hallway by the entrance of stairway #5. Repair one hand wash sink that has become partially detached from the wall behind it in girls bathroom #2408. Repair two hand wash sink faucets that have broken water flow control valves in the boys bathroom on the 2400 hallway by stairway #4. Repair two nonfunctional hand wash sinks in the boys bathroom on the #400 hallway by room #403. Replace broken plumbing drain pipework beneath the sink in art classroom #303. There are major leaks beneath this art class sink due to the broken pipework. A total of eight sinks were observed to require plumbing repair work at the time of inspection.
6	Replace broken and cracked window pane in stairway #4 at the landing between the ground floor and second floor. Repair and stop the sources of major roof and ceiling leaks in the following school locations: in art classroom #303, in classroom #2503, and on the #100 hallway at the entrance of the auditorium theater #109. Replace water stained and missing ceiling panels caused by the leaks in these locations after the sources of the leaks have been fixed. Replace broken door window frame in the special needs class kitchen #405. Repairs for safety are required due to the splintered wood on this broken door window frame.
8	Repair nonfunctional air conditioning systems in the following six school building classrooms: in classroom #413, in classroom #415, in classroom #417, in classroom #519, in classroom #521, and in classroom #523. Repair nonfunctional light fixtures in the staff bathroom on the #400 hallway by custodial closet #414. There was no functional lighting in this staff bathroom at the time of inspection. Priority repairs are required. Repair nonfunctional ceiling light fixtures in the entrance of the boys locker room, and in the boys bathroom on the #400 hallway by room #403.

Additional Comments

GC: School facility sanitation inspection completed.