

Inspection of School

Status Code: A

Old Facility ID _____

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: TRIANGLE MATH AND SCIENCE ACADEMY HS CAMPUS APEX

Location Address: 3570 AMBERLIGHT ROAD

Mailing Addr: 3570 AMBERLIGHT ROAD

City: APEX

State: NC

Zip: 27502

City: APEX

State: NC

Zip: 27502

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	35
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	
TOTAL	1000	85

Additional Comment Sheet Attached

Yes No

Inspection by:

J.D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



Comment Addendum to Inspection Report

Establishment Name: TRIANGLE MATH AND SCIENCE ACADEMY HS CAMPUS **Establishment ID:** 4092440571
APEX

Date: 12/12/2025 **Time In:** 10:00 AM **Time Out:** 12:30 PM

Observations and Corrective Actions

4	Repair bent water supply pipe and flush valve on one urinal in the third floor boys hall bathroom. Repair one nonfunctional toilet in the handicap stall of the first floor hallway boys bathroom. Repair broken door latch on access to the bathroom in the boys locker room. Priority repairs for safety and sanitation are required. Bathroom interior can not be accessed for cleaning and repair due this broken door latch. Staff also can not open this bathroom door to access a student for help in the event of emergencies. Priority repairs for safety are required. Repair and stop the source of the ceiling leak present in the staff bathroom on the first floor hallway and adjacent to custodial closet #139. Replace the water stained ceiling panel in this staff bathroom caused by the leak. Replace missing ceiling panel in the gym lobby staff bathroom.
5	Handicap bathroom stalls hand wash sinks lacked soap dispensers in the second floor boys hall bathroom, in the third floor boys and girls hall bathrooms, and in the first floor boys and girls hall bathrooms. A total of five soap dispensers are necessary at the hand wash sinks in these student bathroom handicap stalls. Repair two loose faucets on the hand wash sinks in the second floor boys hall bathroom. Repair one nonfunctional hand wash sink faucet in the second floor girls hall bathroom. Repair one loose faucet on the hand wash sink in the handicap stall of the boys bathroom on the third floor. Repair one loose hand wash sink faucet in the boys bathroom in the gym lobby.
6	Repair and stop the source of the ceiling leaks present in the gym coaches office #G122A. Replace the water stained ceiling panels caused by the ceiling leaks in this office.

Additional Comments

GC: Gym concession stand has been cooking and preparing hot dogs for sell to the public at athletic events. The gym concession stand must be permitted and inspected by Wake County Environmental Health and Safety Division to be in compliance with state sanitation code in reference to the preparation and sell of food to the public. Until a permit and approval has been acquired from Wake County Environmental Health and Safety Plan Review Division all food preparation for sale to the public must cease and desist immediately. To schedule a Wake County Environmental Health and Safety Division Plan Review site inspection of the gym concession stand for permit requirements please contact Christina Sancha at 919-868-2559.