

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection

Re-inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Visit

Verification of Closure

Status Change

Name of School: OLIVE CHAPEL ELEMENTARY SCHOOL

Location Address: 1751 OLIVE CHAPEL RD

Mailing Addr: 1751 OLIVE CHAPEL RD

City: APEX

State: NC

Zip: 27502-4862

City: APEX

State: NC

Zip: 27502-4862

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	15
TOTAL	1000	100

Additional Comment Sheet Attached

Yes No

Inspection by:

J.D. REHS

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



Comment Addendum to Inspection Report

Establishment Name: OLIVE CHAPEL ELEMENTARY SCHOOL

Establishment ID: 4092440157

Date: 02/27/2025 **Time In:** 9:30 AM **Time Out:** 12:30 PM

Observations and Corrective Actions

- 4 Repair toilet that is leaking around the base of the fixture and onto the floor in the end toilet stall in girls bathroom #181. Repair ceiling leaks in boys bathroom #113 and in girls bathroom #112 around the ceiling vent. Repair and repaint water stained ceiling surfaces in these bathrooms after the sources of the ceiling leaks have been fixed. Repair and repaint damaged lower wall surface in classroom bathroom #211. Repair and reattach loose lower wall base tile in classroom bathroom #220. Replace missing tank lid on toilet in class bathroom of trailer #504. Repair roof and ceiling leaks in the class bathroom of trailer #505. Replace water stained ceiling panels in this bathroom after the roof leak is fixed. Repair and stabilize sagging subfloor behind toilet in the fourth stall of the girls bathroom in the restroom trailer.
- 5 Repair nonfunctional hand wash sink at the entrance into boys bathroom #148.
- 6 Repair major roof and ceiling leaks in the classroom of trailer #505. Repair the water damaged ceiling area in the classroom of trailer #505 after the roof leaks have been fixed. Repair and stabilize the sagging subfloor near the entrance of the class bathroom in trailer #505. Replace missing and broken floor tiles in the classroom of trailer #505. Replace broken floor tiles in the classroom of trailer #503. Repair ceiling leaks in the following main school building locations: in the hallway at the entrance to girls bathroom #147, in the hallway at the entry/exit doors near room #212, in classroom #221, and in classroom #212. Replace water stained ceiling panels in these ceiling leak locations after the causes of the leaks have been fixed. Repaint chipping ceiling surface in the hallway at room #411. Replace missing ceiling panels over the gym stage.
- 8 Replace loose and broken vent cover on the ceiling ventilation ductwork in the gym. Replace missing ceiling vent cover in classroom #202.
- 11 Repair loose sliding and climbing pole on the playground structure adjacent to the drama class trailer. Replace missing coverings on the climbing cables on the web play structure on the playground behind the cafeteria kitchen. Repairs for safety are needed.

Additional Comments

School facility sanitation inspection completed.