

Inspection of School

Status Code: A

Water Supply: Municipal/Community On-Site Supply

Water sample taken today? Inspection

Re-inspection

Name Change

Wastewater: Municipal/Community On-Site System

Yes No

Visit

Verification of Closure

Status Change

Name of School: ST MARY MAGDALENE SCHOOL

Location Address: 625 MAGDALA PL

Mailing Addr: 625 MAGDALA PL

City: APEX

State: NC

Zip: 27502

City: APEX

State: NC

Zip: 27502

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405)	175	** SEE COMMENT SHEET ATTACHED **
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407)	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406)	80	
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408)	100	35
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409)	70	15
6. FLOORS: WALLS: AND CEILING: Floors, walls, and ceilings clean and in good repair 30# (.2410)	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411)	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412)	40	
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413)	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414)	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415)	80	
TOTAL	1000	65

Additional Comment Sheet Attached

Yes No

Inspection by:

J. D. REHS

EHS 1746 - Dunn, Jason

Comment Addendum to Inspection Report

Establishment Name: ST MARY MAGDALENE SCHOOL

Establishment ID: 4092440242

Date: 10/29/2025 **Time In:** 10:00 AM **Time Out:** 12:30 PM

Observations and Corrective Actions

4	Repair one nonfunctional toilet in the girls bathroom on the top floor hallway of the activity building. Repair one nonfunctional toilet in the girls bathroom on the lower floor hallway of the educational building #401. Repair one nonfunctional toilet in the girls bathroom on the top floor hallway of the educational building #401. Repair one toilet that is leaking on the flush valve in the student bathroom in classroom #105. Four toilets total are in need of repair. Replace broken off door on one toilet stall in the boys bathroom in the activity building on the lower floor hallway.
5	Repair one broken and nonfunctional hand wash sink faucet in the girls bathroom on the lower floor hall of the activity building.
6	Repair and stop the source of the ceiling leak present in the drama program dressing room by the gyn stage. Replace the water stained ceiling panel caused by this leak in the dressing room after repairs have been completed.

Additional Comments

GC: Repair broken anchor chain on one of the step swing stands on the playground structure. Safety repair item.