

**Inspection of School**

Status Code: A

Water Supply:  Municipal/Community  On-Site Supply

Water sample taken today?  Inspection  Name Change

Wastewater:  Municipal/Community  On-Site System

Yes  No

Re-inspection

Verification of Closure

Visit

Status Change

Name of School: APEX FRIENDSHIP HIGH SCHOOL

Location Address: 7901 HUMIE OLIVE RD

Mailing Addr: 1551 ROCK QUARRY ROAD

City: APEX State: NC Zip: 27502

City: RALEIGH State: NC Zip: 27610

	Score	Comments
1. WATER SUPPLY: Approved water supply properly located, constructed, and operated, adequate for all requirements 130*; well house clean, no storage 15*; no cross connections 30* (.2405) .....	175	<b>** SEE COMMENT SHEET ATTACHED **</b>
2. SANITARY SEWAGE DISPOSAL: Sewage collected, treated, and disposed of by an approved method 150*; system properly operated and maintained 55* (.2407) .....	205	
3. DRINKING FOUNTAINS: Clean and in good repair 40#; adequate pressure, properly regulated 40# (.2406) .....	80	20
4. TOILET FACILITIES: Walls and ceilings clean, nonabsorbent, washable, and in good repair 30#; fixtures clean and in good repair 40#; floors impervious, kept clean 30# (.2408) .....	100	20
5. LAVATORY FACILITIES: Fixtures clean and in good repair 30#; soap and individual towels or approved hand-drying devices provided 40# (.2409) .....	70	15
6. FLOORS: WALLS: AND CEILINGS: Floors, walls, and ceilings clean and in good repair 30# (.2410) .....	30	15
7. STORAGE SPACES: Clean 20#; storage off floor 20# (.2411) .....	40	
8. LIGHTING AND VENTILATION: Fixtures, grills, vents, blinds, drapes, etc., clean and in good repair 40# (.2412) .....	40	20
9. DRESSING ROOMS AND SHOWERS: Floors, walls, and ceilings clean, in good repair, washable, non-absorbent 30#; fixtures clean, in good repair 40#; facilities for storage of clothes provided, kept clean 20#; soap and towel 10* (.2413) .....	100	
10. SOLID WASTE DISPOSAL: Impervious, cleanable containers with lids, approved type 20*; clean and in good repair 20#; empties as needed, properly disposed of 40# (.2414) .....	80	
11. PREMISES: MISCELLANEOUS: Premises neat, clean 30#; no vector breeding or harborage 20#; pesticides and other toxic materials properly handled and stored 30* (.2415) .....	80	
<b>TOTAL</b>	<b>1000</b>	<b>90</b>

Additional Comment Sheet Attached

Yes  No

Inspection by:

*J D REHS*

EHS 1746 - Dunn, Jason

INSTRUCTIONS Purpose: General Statute 130A-236 requires the Commission for Health Services to adopt rules governing the sanitation of public, private, and religious schools. This form has been developed to record the results of such inspections. Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for: 1. Original to be left with principal. 2. Copy for the local health department. 3. Copy for the Environmental Health Services Section, Division of Environmental Health. Disposition: Please refer to Records Retention and Disposition Schedule 8.B.6., Inspection Records for County/District Health Departments which is published by the North Carolina Division of Archives & History. Additional forms may be ordered from: Division of Environmental Health, 1632 Mail Service Center, Raleigh, NC 27699-1632, (Courier 52-01-00) EHS 1163 (Revised 7/05) Environmental Health Services Section (Review 7/08)



## Comment Addendum to Inspection Report

**Establishment Name:** APEX FRIENDSHIP HIGH SCHOOL

**Establishment ID:** 4092440421

**Date:** 02/13/2025 **Time In:** 9:30 AM **Time Out:** 12:45 PM

### Observations and Corrective Actions

- 3 Repair drinking fountain that has a clogged drain pipe on the hallway adjacent to girls bathroom #3231. Repair the drinking fountain at the stadium home team concession stand. It can not be turned off and the water from this fountain runs constantly.
- 4 There is no water flow to the men's and women's restrooms for both the home team sides and visitor sides of the athletic stadium.. This is due to water line issues. All toilets and urinals in all four of these restrooms are nonfunctional. Priority repairs are needed to restore water flow to these public restrooms. Repair the second toilet in the modular class building boys bathroom. This toilet has a clogged drain pipe. Repair nonfunctional toilet in the staff bathroom in the fine arts building. In boys bathroom #2201 repair the second urinal which has no water flow and the first toilet which is leaking on the plumbing pipework. Repair nonfunctional toilet in the end/handicap stall in boys bathroom #4201. This toilet has a clogged drain pipe. Repair one nonfunctional toilet in girls bathroom #3231. Repair the 6th toilet in girls bathroom #1229. This toilet has poor water flow for flushing. Replace broken toilet seats in the following student bathrooms: boys bathroom #2201, one broken toilet seat, boys bathroom #1201, one broken toilet seat in the 2nd stall. girls bathroom #4233, one broken toilet seat in the 4th stall from end, and in girls bathroom #3231, three broken toilet seats.
- 5 There is no water flow to the men's and women's restrooms for both the home team side and visitor team sides of the athletic stadium. This is due to water supply line issues. The hand wash sink faucets in all four of these men's and women's restrooms are nonfunctional due to no water flow. Priority repairs are needed to restore water flow to the hand wash sinks in these public restrooms. Replace missing hand wash sink that had been removed from the wall in boys bathroom #4201 due to damage. Repair nonfunctional faucet on one hand wash sink also in boys bathroom #4201.
- 6 Repair roof and ceiling leaks in the following school building locations: in the media center and in the main gym over the bleachers. Replace water stained ceiling panel in the media center after ceiling leak is fixed. Repair water damaged, water stained, and possibly mold stained ceiling areas in the gym after the roof leaks are fixed.
- 8 Repair poorly functioning and improperly functioning heating and air conditioning systems in the following school classrooms #4235, #3233, #3213, and #2231.

### Additional Comments

School facility sanitation inspection completed.