

Demerit Score: 8

Date of Insp/Chg: 04/10/2025
Status Code: A

Health Department 92
Current Facility ID 4092500485
Old Facility ID _____

Inspection of Swimming Pool

Water Supply: Municipal/Community On-Site Supply
Wastewater: Municipal/Community On-Site System

Water sample taken today?
 Yes No

Inspection Name Change
 Re-inspection Verification of Closure
 Visit Status Change

Name of Establishment: OLIVE CHAPEL SWIM CLUB POOL

Pool Operator: Doug Shaw
(F, L)

Location Address: 1221 AINSLEY WOODS PLACE

Mailing Addr. 11010 RAVEN RIDGE ROAD

City: APEX State: NC Zip: 27502

City: RALEIGH State: NC Zip: 27614

* Indicates critical item (6-point demerit)

WATER QUALITY: (.2535)

- *1. Water clear enough to clearly see bottom of pool and pool drain **6**
- *2. Disinfectant residual provided by:
 - free chlorine = 5.0 (at least 1.0 ppm or 2.0 ppm where required);
 - bromine = (at least 2.0 ppm); or
 - biguanide = (30 to 50 ppm).....
- *3. Pool water pH = 7.2 (7.2 to 7.8)..... **6**
- *4. Water temperature of heated pool °F; does not exceed 90°F
(swimming pool) or 104°F (spa) **6**
- 5. Daily written records of water quality and test kit kept on site **4**

Comments:

**** SEE COMMENT SHEET ATTACHED ****

POOL MAINTENANCE:

- *6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=200 Field verification complete=Yes **6**
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)... **4**
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) **4**
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537)..... **4**
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523)..... **2**
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521)..... **2**
- 12. Inlets and other fittings in place and in good repair (.2537)..... **4**
- 13. Contrasting band on steps and benches (.2521, .2516, .2532)..... **4**
- 14. Spa timer working properly (.2537)..... **4**

PREMISES:

- *15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) **6**
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) **4**
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537)..... **4**
- 18. Lifeguards present or warning signs posted (.2530) **4**
- 19. Signs prohibit glass containers or pets in pool area(.2530) **4**
- 20. Caution signs posted at hot water spas (.2532) **4**
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ... **4**
- *22. Emergency telephone provided (.2530) **6**

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) **4**
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) **4**
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) **2**
- 26. Valves and pipes identified by color codes or labels (.2518) **2**
- 27. Filter backwash discharged through an air gap (.2513) **2**

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) **2**
- 29. Required fixtures provided, clean, and in good repair (.2526) **2**
- 30. Approved water source, no cross connections (.2512) **2**
- 31. Sewage disposed of in a properly operating sewage system (.2513) **2**
- 32. Floors smooth, slip-resistant, kept clean(.2526) **2**
- 33. Hose bibbs and floor drains provided (.2526) **2**

Comment Sheet Attached

Yes No

Report Received by:

Dunn, Jason

Inspection

Conducted by: J D REAS

EHS I.D. # 1746 - Dunn, Jason

Comment Addendum to Inspection Report

Establishment Name: OLIVE CHAPEL SWIM CLUB POOL

Establishment ID: 4092500485

Date: 04/10/2025 **Time In:** 10:00 AM **Time Out:** 11:30 AM

Observations and Corrective Actions

- 16 Repair bent apart vertical fence rails on section of fencing adjacent to pool entry steps. The bent fencing in this location has a space greater than four inches between the vertical rails. There is a space greater than two inches in height between the pool fence base and the ground on the section of pool fencing parallel to diving well area. The space between fence and ground in this location is four inches in height. Keep service gate entrance adjacent to the pool slide area tightly chained and locked at all times so that the gate can not be pulled open to a space greater than four inches in length between the gate and fence post.
- 21 Reattach loose interior light into the pool wall in the four foot section of the pool adjacent to the sun screen awning area.

Additional Comments

Seasonal pool permit issued on 04/10/2025.

Pool operation permit expires on 10/31/2025.

Liquid chlorine feeder automatic shutoff was functioning properly at the time of pool inspection.

Visible bonding wiring was intact and securely attached to pool pumps at the time of inspection.

Pool is permitted for daylight use only.

VGB data on file matches pool equipment on site.