

**Demerit Score: 8**

Date of Insp/Chg: 04/01/2026  
Status Code: Q

Health Department 92  
Current Facility ID 4092500578  
Old Facility ID \_\_\_\_\_

**Inspection of Swimming Pool**

**Water Supply:**  Municipal/Community  On-Site Supply  
**Wastewater:**  Municipal/Community  On-Site System

**Water sample taken today?**  
 Yes  No

Inspection  Name Change  
 Re-inspection  Verification of Closure  
 Visit  Status Change

Name of Establishment: ABBINGTON Pool Operator: Braxton Wilson  
(F, L)  
Location Address: 101 KELLYRIDGE DR Mailing Addr. 11010 RAVEN RIDGE ROAD  
City: APEX State: NC Zip: 27502 City: RALEIGH State: NC Zip: 27614

**WATER QUALITY: (.2535)**

- \*1. Water clear enough to clearly see bottom of pool and pool drain .....  **6**
- \*2. Disinfectant residual provided by:
  - free chlorine = 7.5 (at least 1.0 ppm or 2.0 ppm where required);
  - bromine = (at least 2.0 ppm); or
  - biguanide = (30 to 50 ppm)..... **6**
- \*3. Pool water pH = 7.4 (7.2 to 7.8).....  **6**
- \*4. Water temperature of heated pool °F; does not exceed 90°F  
(swimming pool) or 104°F (spa) .....  **6**
- 5. Daily written records of water quality and test kit kept on site .....  **4**

\* Indicates critical item (6-point demerit)

**Comments:**

**\*\* SEE COMMENT SHEET ATTACHED \*\***

**POOL MAINTENANCE:**

- \*6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=450 Field verification complete=Yes  **6**
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)...  **4**
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) .....  **4**
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537).....  **4**
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523).....  **2**
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521).....  **2**
- 12. Inlets and other fittings in place and in good repair (.2537).....  **4**
- 13. Contrasting band on steps and benches (.2521, .2516, .2532).....  **4**
- 14. Spa timer working properly (.2537).....  **4**

**PREMISES:**

- \*15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) .....  **6**
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) .....  **4**
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537).....  **4**
- 18. Lifeguards present or warning signs posted (.2530) .....  **4**
- 19. Signs prohibit glass containers or pets in pool area(.2530) .....  **4**
- 20. Caution signs posted at hot water spas (.2532) .....  **4**
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ...  **4**
- \*22. Emergency telephone provided (.2530) .....  **6**

**EQUIPMENT ROOM:**

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) .....  **4**
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) .....  **4**
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) .....  **2**
- 26. Valves and pipes identified by color codes or labels (.2518) .....  **2**
- 27. Filter backwash discharged through an air gap (.2513) .....  **2**

**DRESSING AND SANITARY FACILITIES:**

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) .....  **2**
- 29. Required fixtures provided, clean, and in good repair (.2526) .....  **2**
- 30. Approved water source, no cross connections (.2512) .....  **2**
- 31. Sewage disposed of in a properly operating sewage system (.2513) .....  **2**
- 32. Floors smooth, slip-resistant, kept clean(.2526) .....  **2**
- 33. Hose bibbs and floor drains provided (.2526) .....  **2**

**Comment Sheet Attached**

Yes  No

Report Received by:



Inspection Conducted by: Anna Wang

EHS I.D. # 2482 - Walls, Anna

## Comment Addendum to Inspection Report

**Establishment Name:** ABBINGTON

**Establishment ID:** 4092500578

**Date:** 04/01/2026 **Time In:** 2:00 PM **Time Out:** 4:00 PM

### Observations and Corrective Actions

- 16 .2528 (a)(2); Picnic table in playground directly beside fence where children could climb pool fence. Discarded pallet directly beside fence providing handhold/foothold. Openings in the barrier shall not allow passage of a four-inch-diameter sphere and shall provide no external handholds or footholds. Solid barriers that do not have openings shall not contain indentations or protrusions except for normal construction tolerances and tooled masonry joints. Corrected during inspection- CPO moved more than 3' from fence.
- 17 .2537(2); Small area of concrete decking separated greater than 1/2" by right side of slide. CPO placed work order. Have repaired before re-inspection. Decks shall be kept free of trip hazards or offsets greater than 1/2" due to deterioration or changes from original deck profile.

### Additional Comments

Pool permit was not issued today. Pump motor was replaced in December 2025. Proof of electrical permit could not be provided. Town of Apex online building permit records showed last electrical permit pulled 2022. Contact inspections for Town of Apex and pull electrical permit to get pump inspected. Contact EHS when completed and provide documentation. Pay pool reinspection fee to Wake Co EH.

VGB approval data on file matches pool equipment present on site.  
Automatic shutoff of liquid chlorine feeder was functioning properly at the time of inspection.