

Inspection of Swimming Pool

Water Supply: Municipal/Community On-Site Supply
Wastewater: Municipal/Community On-Site System

Water sample taken today?
 Yes No

Inspection Name Change
 Re-inspection Verification of Closure
 Visit Status Change

Name of Establishment: OLIVE CHAPEL PARK POOL

Pool Operator: Michael James
(F, L)

Location Address: 1780 GRANDE CHATEAU LN

Mailing Addr. 1401 SUNDAY DRIVE, SUITE 116

City: APEX State: NC Zip: 27502

City: RALEIGH State: NC Zip: 27607

WATER QUALITY: (.2535)

- *1. Water clear enough to clearly see bottom of pool and pool drain **6**
- *2. Disinfectant residual provided by:
 - free chlorine = 3.0 (at least 1.0 ppm or 2.0 ppm where required);
 - bromine = (at least 2.0 ppm); or
 - biguanide = (30 to 50 ppm)..... **6**
- *3. Pool water pH = 7.4 (7.2 to 7.8)..... **6**
- *4. Water temperature of heated pool °F; does not exceed 90°F
(swimming pool) or 104°F (spa) **6**
- 5. Daily written records of water quality and test kit kept on site **4**

* Indicates critical item (6-point demerit)

Comments:

**** SEE COMMENT SHEET ATTACHED ****

POOL MAINTENANCE:

- *6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=120 Field verification complete=Yes **6**
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)... **4**
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) **4**
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537)..... **4**
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523)..... **2**
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521)..... **2**
- 12. Inlets and other fittings in place and in good repair (.2537)..... **4**
- 13. Contrasting band on steps and benches (.2521, .2516, .2532)..... **4**
- 14. Spa timer working properly (.2537)..... **4**

PREMISES:

- *15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) **6**
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) **4**
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537)..... **4**
- 18. Lifeguards present or warning signs posted (.2530) **4**
- 19. Signs prohibit glass containers or pets in pool area(.2530) **4**
- 20. Caution signs posted at hot water spas (.2532) **4**
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ... **4**
- *22. Emergency telephone provided (.2530) **6**

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) **4**
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) **4**
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) **2**
- 26. Valves and pipes identified by color codes or labels (.2518) **2**
- 27. Filter backwash discharged through an air gap (.2513) **2**

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) **2**
- 29. Required fixtures provided, clean, and in good repair (.2526) **2**
- 30. Approved water source, no cross connections (.2512) **2**
- 31. Sewage disposed of in a properly operating sewage system (.2513) **2**
- 32. Floors smooth, slip-resistant, kept clean(.2526) **2**
- 33. Hose bibbs and floor drains provided (.2526) **2**

Comment Sheet Attached

Yes No

Report Received by:

Handwritten signature

Inspection

Conducted by: J.D. REHS

EHS I.D. # 1746 - Dunn, Jason

Comment Addendum to Inspection Report

Establishment Name: OLIVE CHAPEL PARK POOL

Establishment ID: 4092500927

Date: 04/25/2025 **Time In:** 10:00 AM **Time Out:** 12:00 PM

Observations and Corrective Actions

- 16 The base of the chain length pool perimeter fence has become loose on the shared section of fencing between the pool and tennis court. As a temporary fix the pool management company has used zip ties to reattach the fence mesh to the guide wire to secure and anchor the mesh. New fencing should be installed along the tennis court as a permanent repair. Repair bent vertical railings adjacent to pool signs and rescue equipment. There is a space of four to four and a half inches between the bent vertical railings. This space should not exceed four inches. Weeds and shrub growth should be trimmed away from and out of the pool fencing to prevent damage to the fence.
- 18 Weeds and shrubs on the pool fencing are blocking the view of the No Lifeguard on Duty sign. These weeds and shrubs should be trimmed to keep the No Lifeguard on Duty sign visible to pool patrons.

Additional Comments

Seasonal pool permit issued on 4/25/2025.

Pool operation permit expires on 10/31/2025.

Visible bonding wiring was intact and securely attached to pool pumps at the time of inspection.

Automatic shutoff for liquid chlorine feeder was functioning properly at the time of inspection.

Equipment on site matches VGB data on file.

Flow meter was functioning properly at the time of inspection.

Pool is permitted for daylight use only. No night time swimming.