

Demerit Score: 20

Date of Insp/Chg: 04/22/2025  
Status Code: A

Health Department 92

Current Facility ID 4092501129

Old Facility ID

Inspection of Swimming Pool

Water Supply:  Municipal/Community  On-Site Supply  
Wastewater:  Municipal/Community  On-Site System

Water sample taken today?

Yes  No

Inspection  
 Re-inspection  
 Visit

Name Change  
 Verification of Closure  
 Status Change

Name of Establishment: STILLWATER POOL

Pool Operator: Michael James  
(F, L)

Location Address: 3025 CURLING CREEK DR

Mailing Addr. 4112 BLUE RIDGE RD., SUITE 100

City: APEX State: NC Zip: 27502

City: RALEIGH State: NC Zip: 27612

WATER QUALITY: (.2535)

\* Indicates critical item (6-point demerit)

- \*1. Water clear enough to clearly see bottom of pool and pool drain .....  6
- \*2. Disinfectant residual provided by:
  - free chlorine = 2.0 (at least 1.0 ppm or 2.0 ppm where required);
  - bromine = (at least 2.0 ppm); or
  - biguanide = (30 to 50 ppm).....  6
- \*3. Pool water pH = 7.7 (7.2 to 7.8).....  6
- \*4. Water temperature of heated pool °F; does not exceed 90°F  
(swimming pool) or 104°F (spa) .....  6
- 5. Daily written records of water quality and test kit kept on site .....  4

Comments:

\*\* SEE COMMENT SHEET ATTACHED \*\*

POOL MAINTENANCE:

- \*6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=170 Field verification complete=Yes  6
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)...  4
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) .....  4
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537).....  4
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523).....  2
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521).....  2
- 12. Inlets and other fittings in place and in good repair (.2537).....  4
- 13. Contrasting band on steps and benches (.2521, .2516, .2532).....  4
- 14. Spa timer working properly (.2537).....  4

PREMISES:

- \*15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) .....  6
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) .....  4
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537).....  4
- 18. Lifeguards present or warning signs posted (.2530) .....  4
- 19. Signs prohibit glass containers or pets in pool area(.2530) .....  4
- 20. Caution signs posted at hot water spas (.2532) .....  4
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ...  4
- \*22. Emergency telephone provided (.2530) .....  6

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) .....  4
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) .....  4
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) .....  2
- 26. Valves and pipes identified by color codes or labels (.2518) .....  2
- 27. Filter backwash discharged through an air gap (.2513) .....  2

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) .....  2
- 29. Required fixtures provided, clean, and in good repair (.2526) .....  2
- 30. Approved water source, no cross connections (.2512) .....  2
- 31. Sewage disposed of in a properly operating sewage system (.2513) .....  2
- 32. Floors smooth, slip-resistant, kept clean(.2526) .....  2
- 33. Hose bibbs and floor drains provided (.2526) .....  2

Comment Sheet Attached

Yes  No

Report Received by:

*Anto R.*

Inspection

*Maria Powell*

Conducted by:

EHS I.D. #

2587 - Powell, Maria

## Comment Addendum to Inspection Report

**Establishment Name:** STILLWATER POOL

**Establishment ID:** 4092501129

**Date:** 04/22/2025 **Time In:** 10:30 AM **Time Out:** 12:30 PM

### Observations and Corrective Actions

- 8 2537. Observed heavy debris in skimmer baskets Surface skimmers shall be maintained clean.
- 16 2537. Observed one entry door the pool that would not self-latch. CPO adjusted door to self-close and self-latch during inspection.
- 17 2537. Observed several ½ inch or greater, trip hazard in some areas around the pool deck. Trip hazards shall be 1/2 inch or less offset. CPO filled trip hazards during inspection.  
2537. Observed deck chair within 4 ft of pool edge. Outdoor pools shall provide 6 ft or more of deck clearance.
- 22 2530. Phone number posted next to emergency phone is incorrect. Emergency phone shall provide accurate phone number. Correct phone number posted during inspection.
- 29 .2526 Observed no soap available at hand sinks and soiled water fountains. Fixtures shall be maintained clean.

### Additional Comments

In regards to the bonding wire, No imminent hazard found in pump room at time of inspection. Visible bonding wire attached and intact to pump. Have an electrician evaluate all the components to determine function, if not done so prior to permitting inspection. If an electrician finds a repair is needed, obtain an electrical permit from the appropriate municipality, and have the corrections inspected. Flow rate of pump =340gpm