

**Inspection of Swimming Pool**

**Water Supply:**  Municipal/Community  On-Site Supply  
**Wastewater:**  Municipal/Community  On-Site System

**Water sample taken today?**  
 Yes  No

Inspection  Name Change  
 Re-inspection  Verification of Closure  
 Visit  Status Change

Name of Establishment: WEST VILLAGE POOL

Pool Operator: Jarred richardson  
(F, L)

Location Address: 2005 LEO DR

Mailing Addr. 2800 SUMNER BLVD. SUITE # 106

City: APEX State: NC Zip: 27502

City: RALEIGH State: NC Zip: 27616

**WATER QUALITY: (.2535)**

\* Indicates critical item (6-point demerit)

- \*1. Water clear enough to clearly see bottom of pool and pool drain .....  **6**
- \*2. Disinfectant residual provided by:
  - free chlorine = 7.5 (at least 1.0 ppm or 2.0 ppm where required);
  - bromine = (at least 2.0 ppm); or
  - biguanide = (30 to 50 ppm).....  **6**
- \*3. Pool water pH = 7.4 (7.2 to 7.8).....  **6**
- \*4. Water temperature of heated pool °F; does not exceed 90°F  
(swimming pool) or 104°F (spa) .....  **6**
- 5. Daily written records of water quality and test kit kept on site .....  **4**

**Comments:**

**\*\* SEE COMMENT SHEET ATTACHED \*\***

**POOL MAINTENANCE:**

- \*6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=200 Field verification complete=Yes  **6**
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)...  **4**
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) .....  **4**
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537).....  **4**
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523).....  **2**
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521).....  **2**
- 12. Inlets and other fittings in place and in good repair (.2537).....  **4**
- 13. Contrasting band on steps and benches (.2521, .2516, .2532).....  **4**
- 14. Spa timer working properly (.2537).....  **4**

**PREMISES:**

- \*15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) .....  **6**
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) .....  **4**
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537).....  **4**
- 18. Lifeguards present or warning signs posted (.2530) .....  **4**
- 19. Signs prohibit glass containers or pets in pool area(.2530) .....  **4**
- 20. Caution signs posted at hot water spas (.2532) .....  **4**
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ...  **4**
- \*22. Emergency telephone provided (.2530) .....  **6**

**EQUIPMENT ROOM:**

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) .....  **4**
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) .....  **4**
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) .....  **2**
- 26. Valves and pipes identified by color codes or labels (.2518) .....  **2**
- 27. Filter backwash discharged through an air gap (.2513) .....  **2**

**DRESSING AND SANITARY FACILITIES:**

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) .....  **2**
- 29. Required fixtures provided, clean, and in good repair (.2526) .....  **2**
- 30. Approved water source, no cross connections (.2512) .....  **2**
- 31. Sewage disposed of in a properly operating sewage system (.2513) .....  **2**
- 32. Floors smooth, slip-resistant, kept clean(.2526) .....  **2**
- 33. Hose bibbs and floor drains provided (.2526) .....  **2**

**Comment Sheet Attached**

Yes  No

Report Received by:



Inspection

Conducted by: Maria Powell

EHS I.D. # 2587 - Powell, Maria

## Comment Addendum to Inspection Report

**Establishment Name:** WEST VILLAGE POOL

**Establishment ID:** 4092501254

**Date:** 04/16/2025 **Time In:** 10:00 AM **Time Out:** 11:45 AM

### Observations and Corrective Actions

- 5 .2535 Only records available onsite are dated 2024. Current pool chemistry records have not been recorded at this time. .  
Records shall be taken 2 times daily.
- 17 2537. Observed several ½ inch or greater, trip hazard in some areas around the pool deck. Trip hazards shall be 1/2 inch or less offset. CPO filled trip hazards during inspection.
- 24 .2518.Observed flow meter reading recorded on VGB letter for feature pump. However, Flow meter is not available onsite for the feature pump. Equipment shall be in good repair. CPO onsite agreed to place order for flow meter installation. Replace flow meter.
- 29 2526.Observed missing knob for hot water at shower. CPO installed new knob during inspection. Observed soiled toilets inside restrooms. Fixtures shall be maintained clean.

### Additional Comments

In regards to the bonding wire, No imminent hazard found in pump room at time of inspection. Visible bonding wire attached and intact to pump. Have an electrician evaluate all the components to determine function, if not done so prior to permitting inspection. If an electrician finds a repair is needed, obtain an electrical permit from the appropriate municipality, and have the corrections inspected.  
Flow rate of pump = 200gpm