

Demerit Score: 0

Date of Insp/Chg: 06/20/2025
Status Code: A

Health Department 92
Current Facility ID 4092531085
Old Facility ID

Inspection of Swimming Pool

Water Supply: Municipal/Community On-Site Supply
Wastewater: Municipal/Community On-Site System

Water sample taken today? Yes No
 Inspection Name Change
 Re-inspection Verification of Closure
 Visit Status Change

Name of Establishment: SPRINGHILL SUITES POOL Pool Operator: Robert Costello (F, L)
Location Address: 1100 MARCO DR Mailing Addr. 1100 MARCO DR
City: APEX State: NC Zip: 27502 City: APEX State: NC Zip: 27502

WATER QUALITY: (.2535)

- *1. Water clear enough to clearly see bottom of pool and pool drain 6
*2. Disinfectant residual provided by: free chlorine = 2.0 (at least 1.0 ppm or 2.0 ppm where required); bromine = (at least 2.0 ppm); or biguanide = (30 to 50 ppm)..... 6
*3. Pool water pH = 7.4 (7.2 to 7.8)..... 6
*4. Water temperature of heated pool 83.0 °F; does not exceed 90°F (swimming pool) or 104°F (spa) 6
5. Daily written records of water quality and test kit kept on site 4

* Indicates critical item (6-point demerit)

Comments:

** SEE COMMENT SHEET ATTACHED **

POOL MAINTENANCE:

- *6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=70 Field verification complete=Yes 6
7. Pool walls and floor kept clean, free of debris and in good repair (.2537)... 4
8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) 4
9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537)..... 4
10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523)..... 2
11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521)..... 2
12. Inlets and other fittings in place and in good repair (.2537)..... 4
13. Contrasting band on steps and benches (.2521, .2516, .2532)..... 4
14. Spa timer working properly (.2537)..... 4

PREMISES:

- *15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) 6
16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) 4
17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537)..... 4
18. Lifeguards present or warning signs posted (.2530) 4
19. Signs prohibit glass containers or pets in pool area(.2530) 4
20. Caution signs posted at hot water spas (.2532) 4
21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ... 4
*22. Emergency telephone provided (.2530) 6

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) 4
24. Approved pump, filter, and flow meter operating properly (2518, .2519) 4
25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) 2
26. Valves and pipes identified by color codes or labels (.2518) 2
27. Filter backwash discharged through an air gap (.2513) 2

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) 2
29. Required fixtures provided, clean, and in good repair (.2526) 2
30. Approved water source, no cross connections (.2512) 2
31. Sewage disposed of in a properly operating sewage system (.2513) 2
32. Floors smooth, slip-resistant, kept clean(.2526) 2
33. Hose bibbs and floor drains provided (.2526) 2

Comment Sheet Attached

Yes No

Report Received by:

Handwritten signatures of the inspector and the facility representative.

Inspection Conducted by: K Crowder EHS I.D. # 2048 - Crowder, Karla