

Demerit Score: 4

Date of Insp/Chg: 10/23/2025
Status Code: A

Health Department 92
Current Facility ID 4092531110
Old Facility ID _____

Inspection of Swimming Pool

Water Supply: Municipal/Community On-Site Supply
Wastewater: Municipal/Community On-Site System

Water sample taken today?
 Yes No

Inspection Name Change
 Re-inspection Verification of Closure
 Visit Status Change

Name of Establishment: BIG BLUE SWIM SCHOOL POOL BEAVER CREEK

Pool Operator:
(F, L)

Location Address: 1041 BEAVER CREEK COMMONS DR

Mailing Addr. 88 W PACES FRY RD, UNIT 2020

City: APEX State: NC Zip: 27502

City: ATLANTA State: GA Zip: 30355

WATER QUALITY: (.2535)

* Indicates critical item (6-point demerit)

- *1. Water clear enough to clearly see bottom of pool and pool drain 6
- *2. Disinfectant residual provided by:
 - free chlorine = 2.0 (at least 1.0 ppm or 2.0 ppm where required);
 - bromine = (at least 2.0 ppm); or
 - biguanide = (30 to 50 ppm)..... 6
- *3. Pool water pH = 7.6 (7.2 to 7.8)..... 6
- *4. Water temperature of heated pool 87.0 °F; does not exceed 90°F
(swimming pool) or 104°F (spa) 6
- 5. Daily written records of water quality and test kit kept on site 4

Comments:

**** SEE COMMENT SHEET ATTACHED ****

POOL MAINTENANCE:

- *6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=385 Field verification complete=Yes 6
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)... 4
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) 4
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537)..... 4
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523)..... 2
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521)..... 2
- 12. Inlets and other fittings in place and in good repair (.2537)..... 4
- 13. Contrasting band on steps and benches (.2521, .2516, .2532)..... 4
- 14. Spa timer working properly (.2537)..... 4

PREMISES:

- *15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) 6
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) 4
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537)..... 4
- 18. Lifeguards present or warning signs posted (.2530) 4
- 19. Signs prohibit glass containers or pets in pool area(.2530) 4
- 20. Caution signs posted at hot water spas (.2532) 4
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ... 4
- *22. Emergency telephone provided (.2530) 6

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) 4
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) 4
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) 2
- 26. Valves and pipes identified by color codes or labels (.2518) 2
- 27. Filter backwash discharged through an air gap (.2513) 2

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) 2
- 29. Required fixtures provided, clean, and in good repair (.2526) 2
- 30. Approved water source, no cross connections (.2512) 2
- 31. Sewage disposed of in a properly operating sewage system (.2513) 2
- 32. Floors smooth, slip-resistant, kept clean(.2526) 2
- 33. Hose bibbs and floor drains provided (.2526) 2

Comment Sheet Attached

Yes No

Report Received by:



Inspection
Conducted by:

J.D. REAS

EHS I.D. # 1746 - Dunn, Jason

Comment Addendum to Inspection Report

Establishment Name: BIG BLUE SWIM SCHOOL POOL BEAVER CREEK

Establishment ID: 4092531110

Date: 10/23/2025 **Time In:** 2:00 PM **Time Out:** 3:30 PM

Observations and Corrective Actions

- 8 Replace missing weir in one of the pool skimmers.

Additional Comments

Reinspection of swimming pool to verify that the pool entry door noted on prior inspections is now self closing and self latching. Spoke with pool facility maintenance and design director, Eli Youmans. Mr. Youmans provided information including prior pool fire safety inspections and certificate of occupancy data that the swimming pool entry door can be kept in a locked mode which allows it to be self closing and self latching when used. Mr. Youmans and the pool general manager Sarah Pennington stated that the pool will only operate when the door is kept on this locked setting. The pool door was self closing and self latching when it was checked on the locked setting at the time of inspection. Normal operation of the pool facility can now restart. A door attendant is no longer required at the entrance door during hours of operation when the public uses the pool. The pool operation permit is back to a full active status for the remainder of its annual term.