

Inspection of Swimming Pool

Water Supply: Municipal/Community On-Site Supply
Wastewater: Municipal/Community On-Site System

Water sample taken today?
 Yes No

Inspection Name Change
 Re-inspection Verification of Closure
 Visit Status Change

Name of Establishment: PROVIDENCE AT YATES POND POOL

Pool Operator:
(F, L)

Location Address: 2408 STONINGTON DR

Mailing Addr. 160 NE MAYNARD RD, SUITE 210

City: APEX State: NC Zip: 27523

City: CARY State: NC Zip: 27513

* Indicates critical item (6-point demerit)

WATER QUALITY: (.2535)

- *1. Water clear enough to clearly see bottom of pool and pool drain 6
- *2. Disinfectant residual provided by:
 - free chlorine = 5.0 (at least 1.0 ppm or 2.0 ppm where required);
 - bromine = (at least 2.0 ppm); or
 - biguanide = (30 to 50 ppm)..... 6
- *3. Pool water pH = 7.4 (7.2 to 7.8)..... 6
- *4. Water temperature of heated pool °F; does not exceed 90°F
(swimming pool) or 104°F (spa) 6
- 5. Daily written records of water quality and test kit kept on site 4

Comments:

** SEE COMMENT SHEET ATTACHED **

POOL MAINTENANCE:

- *6. Submerged suction outlets meet ASME/ANSI A112.19.8-2007. Single drains protected.(.2537, .2539) GPM=152 Field verification complete=Yes 6
- 7. Pool walls and floor kept clean, free of debris and in good repair (.2537)... 4
- 8. Surface skimmers (with weirs, baskets and covers) or gutters clean, in good repair, and functioning properly, no floating debris (.2518, .2537) 4
- 9. Depth markings and no diving markers or signs visible and properly located (.2523, .2537)..... 4
- 10. Safety ropes with floats and contrasting color bands provided at shallow area breakpoints (.2515, .2523)..... 2
- 11. Diving equipment, ladders, steps and handrails properly placed, in good repair (.2517, .2521)..... 2
- 12. Inlets and other fittings in place and in good repair (.2537)..... 4
- 13. Contrasting band on steps and benches (.2521, .2516, .2532)..... 4
- 14. Spa timer working properly (.2537)..... 4

PREMISES:

- *15. Body hook and ring buoy with throw rope or lifeguard with rescue tube provided and properly located (.2530, .2537) 6
- 16. Fence or barrier with self-closing, self-latching gates properly constructed and maintained (.2528, .2537) 4
- 17. Decks unobstructed, properly drained, free of trip hazards (.2522, .2537)..... 4
- 18. Lifeguards present or warning signs posted (.2530) 4
- 19. Signs prohibit glass containers or pets in pool area(.2530) 4
- 20. Caution signs posted at hot water spas (.2532) 4
- 21. Pool and deck lighting provided at pools that operate at night (.2524, .2537) ... 4
- *22. Emergency telephone provided (.2530) 6

EQUIPMENT ROOM:

- 23. Chlorine or bromine automatic feeders that meet NSF Standard 50 (.2535) 4
- 24. Approved pump, filter, and flow meter operating properly (2518, .2519) 4
- 25. Equipment and chemicals kept in a dry, well-ventilated enclosure (.2533, .2534, .2537) 2
- 26. Valves and pipes identified by color codes or labels (.2518) 2
- 27. Filter backwash discharged through an air gap (.2513) 2

DRESSING AND SANITARY FACILITIES:

- 28. Bathroom or rest rooms accessible; shower sign posted (.2526) 2
- 29. Required fixtures provided, clean, and in good repair (.2526) 2
- 30. Approved water source, no cross connections (.2512) 2
- 31. Sewage disposed of in a properly operating sewage system (.2513) 2
- 32. Floors smooth, slip-resistant, kept clean(.2526) 2
- 33. Hose bibbs and floor drains provided (.2526) 2

Comment Sheet Attached

Yes No

Report Received by:

[Handwritten signatures]

Inspection Conducted by: *Carla G Pressley*

EHS I.D. # 2800 - Pressley, Carla

Comment Addendum to Inspection Report

Establishment Name: PROVIDENCE AT YATES POND POOL

Establishment ID: 4092501154

Date: 05/01/2026 **Time In:** 11:00 AM **Time Out:** 12:00 PM

Temperature Observations

| Item | Location | Temp | Item | Location | Temp | Item | Location | Temp |
|-------|----------|------|-------|------------|------|-------|--------------|------|
| water | shower | 72 | water | men's room | 70 | water | women's room | 68 |

Observations and Corrective Actions

- 7 .2537(14) Keep pool surface and pool floor free of debris.
Dirt and debris present on pool floor.
- 8 .2518(k) Keep skimmers free of debris so skimmers are capable of operating per manufacturer instruction.
Plant debris found in skimmers.
- 22 .2530(f) Signage with legible letters providing dialing instructions, address of pool and pool telephone number shall be posted at the emergency phone.
Signage for pool dialing instructions, pool address, and pool telephone number was extremely faded and illegible. EHS had CPO rewrite this information with a permanent marker. ***CORRECTED DURING INSPECTION (CDI)***
- .2530(f) Emergency phone shall remain operable.
Pool telephone does not produce an audible ring when called. South Eastern phone company repair personnel replaced phone during inspection. ***CDI***

Additional Comments

No Night Swimming. 54,574 gal; 152gpm min turnover flowrate. Flow Reduction required on new drain covers, so a functional flowmeter required at all times. VGB date based on Feature Drain covers.